


Magnetics for DC-DC converters

Electrical

potential across (v)

current thro' (i)



Magnetic

potential \Rightarrow mmf
magnetomotive force

flow $\Rightarrow \frac{d\phi}{dt}$

FARADAY EQN.

AMPERE'S RULE

Electric

Magnetic.

$\mathcal{V} = N \frac{d\phi}{dt}$

$Ni = \text{mmf}$

$Ni = \int H \cdot dl$

$Ni = H \cdot lm$

$H = \frac{Ni}{lm}$

i

$\frac{d\phi}{dt}$

N

Number

of turns of the winding.

$$v = N \frac{d\phi}{dt}$$


$$\text{mmf} = \underline{\underline{Ni}}$$

power :

$$\underline{\underline{v}} \cdot \underline{\underline{i}} = \text{watts}$$

$$\left(N \frac{d\phi}{dt} \right) \cdot i = \text{watts}$$

$$\underline{\underline{\text{mmf}}} \cdot \underline{\underline{\frac{d\phi}{dt}}} = \text{watts.}$$



$$B = \mu H$$

$$\frac{\phi}{A_c} = \mu \frac{Ni}{lm}$$

$$\phi = \frac{Ni}{\left(\frac{lm}{\mu A_c}\right)} = \frac{Ni}{\mathcal{R}} = \frac{mmf}{\mathcal{R}}$$

$$\phi = \frac{\text{mmf}}{R} = \left(\frac{1}{R}\right) \cdot \text{mmf}$$

$\underline{\phi} = \underline{C} \underline{V}$ electrical equivalent

$\Lambda = \frac{1}{R}$ permeance
 (capacitance) concept

$\underline{\phi} = \underline{\Lambda} \cdot \underline{\text{mmf}}$

$$\phi = \mu \cdot Ni$$

$$N \frac{d\phi}{dt} = \mu \cdot N^2 \frac{di}{dt}$$

$$V = \underbrace{\mu N^2}_{\substack{\text{inductance} \\ \text{value}}} \frac{di}{dt} = L \frac{di}{dt}$$

$$\underline{L} = \underline{\mu} N^2$$

obtained from electrical design.

$\underline{L} \rightarrow A_L \text{ factor } nH/\text{turns}^2$

$$N = \sqrt{\frac{L}{\mu}}$$

$$L = \Lambda N^2$$

$$= \frac{1}{Q} \cdot N^2 = \left(\frac{\mu A_c}{l_m} \right) \cdot N^2$$

$$\underline{L} = \underline{\mu_0 \mu_r A_c} \underline{N^2}$$

\downarrow
 $4\pi \times 10^{-7} \text{ H/m}$

Electrical

L, i

\mathcal{V}_L

$\mathcal{E} \leftrightarrow \text{joules}$



Mechanical

A_c

A_w


$B_{\text{sat}} \leftrightarrow \text{material}$

N

gauge of Copper

Energy

$$\mathcal{E}_{\max} = \frac{1}{2} L I_m^2$$



$$I_m = \left(I_{av} + \frac{\Delta i_L}{2} \right)$$

$$\mathcal{E} = \frac{1}{2} L I_m^2 =$$


$$\frac{1}{2} \cdot \underbrace{L I_m} \cdot \underbrace{I_m}$$

$$\boxed{A_w}$$

$$\mathcal{V} = N \frac{d\phi}{dt} = L \frac{di}{dt}$$

$$= N \phi_m = L I_m$$

$$= N \boxed{A_c} B_m = L I_m$$




$$A_w > N A_{wire}$$

$$A_w > N a_{\text{wire}}$$

$$J = 3 \text{ A/mm}^2$$

$$3 \times 10^6 \text{ A/m}^2$$

$$2 \text{ A/mm}^2 \text{ to } 5 \text{ A/mm}^2$$



J current density Amps/m^2
 A/mm^2

$$\textcircled{J} = \frac{I_{rms}}{A_{wire}} = \frac{I_m / K_c}{A_{wire}} \quad \Leftarrow$$


$$A_{wire} = \frac{I_{rms}}{J}$$

$$I_m = K_c J A_{wire}$$

$$A_w > N a_{\text{wire}}$$

$$\frac{N I_{\text{rms}}}{J} = \frac{N I_m}{K_c J}$$

$$I_m : \frac{A_w K_c J}{N}$$



Airgaps

A_w

$K_w A_w$

$K_w < 1$

inductors = 0.6

transformers = 0.2 to 0.4

$$K_w A_w > N A_{\text{wire}}$$

$$K_w A_w = \frac{N I_m}{K_c J}$$

$$I_m = \frac{K_w K_c J A_w}{N}$$

$$\mathcal{E} = \frac{1}{2} \cdot L I_m \cdot I_m$$

$$= \frac{1}{2} \cdot \cancel{N} \circledast A_c B_m \cdot \frac{K_c K_w \circledast A_w J}{\cancel{N}}$$

$$A_w A_c = A_p = \frac{2\mathcal{E}}{K_c K_w J B_m}$$