

Module 2

Lecture 12: Non destructive Evaluation

- (1) Non-destructive test (NDT)
- (2) Non-destructive evaluation (NDE)
- (3) Non-destructive inspection (NDI)
 - Inspection methods
 - continuous / intermittent
 - Health monitoring.

To detect the structural failure (damage - local)

- Ultrasonic inspection - most commonly practiced technique in SHM

Basic principle

In a infinite solid medium, Elastic waves can propagate in ① mode

① Pressure wave (P waves)

② Shear wave (S waves)

If the medium is bounded, then these wave reflect @ the boundaries to form a complicated wave pattern.

- Guided waves, which remain contained within the wave guide

Lamb waves are guided waves, travelling along the plate

Rayleigh waves are guided waves, constrained to the surface

Love waves are also guided waves, which travel in layered materials. Stoneley waves are guided waves, constrained to material interface.

Ultrasonic Non-destructive Evaluation (NDE) rely on elastic wave propagation and its reflection within the material.

These wave-field disturbances are caused due to local damage and any other defects that are present.

Any disturbance caused to this wave field is an indication of presence of damage is analyzed

Ultrasonic waves involve the following measurements:

- 1) TOF : time of flight, wave transit or delay
- 2) path length
- 3) frequency
- 4) phase angle
- 5) amplitude
- 6) acoustic impedance
- 7) angle of wave deflection (refraction, reflection)

Techniques of ultrasonic method

- 1) pulse - Echo method
- 2) pulse - transmission and pitch - catch method
- 3) pulse - resonance method

Procedure

- An ultrasonic probe (commonly used is a piezo-electric) placed on the surface of the member induces waves in the material
- These probes establish contact with the structure using special coupling gels
- Based on incidence of the transducer, with the surface of the member

It generates P, S wave and its combination

- These waves detect anomalies around the sound path.

- In pitch-echo method, defects are detected in the form of echoes

- In pitch-catch method, flaws are detected by wave dispersion and its attenuation due to damage

Major drawbacks of using ultrasonic method

- Sound path traverses only on a small portion of the material volume hence, Transducer should be moved, to cover a large volume
 - This is time-consuming

Alternatively, we can use C-scan, but they are expensive

- ultrasonic waves cannot be induced normal to the surface of the structure

Hence, cracks which are normal (or) to the surface cannot be detected readily by this beam.

But guided waves can be used to detect such flaws.

Long waves are commonly used guided waves

- They are used to detect damage/flaws in sheet metal, airframes, large containers and pipes.

Lamb waves can detect

- cracks
- inclusions
- disbonding in metallic and composite structures
- They are very useful for detecting damage in thin plates & shells.

Rayleigh waves are more useful in detecting surface defects

Embedded NDF

Server network, used for monitoring can be completely embedded (permanently fixed) into the structure. These sensors can be used for monitoring.

Passive SHM

uses passive sensors that are monitored over a period of time
- monitored data will be useful in updating the system characteristics

Example 1- Passive SHM

- 1) load
- 2) stress
- 3) Environmental conditions
- 4) acoustic emissions from cracks
etc

Passive STM only listens to the structure
It ~~doesn't~~ interact with the structure

Active STM detects presence & damage and
also estimates its extent and severity

One of the Active STM is piezoelectric wafer Active Sensor (PWAS)

- These sensors send signal (Lamb waves) and also receive (GWS waves
to identify presence & damage in the structure

(cracks, delaminations, debonding, corrosion etc)

In the plots, ultrasonic guided waves appear as Lamb waves and shear horizontal waves.

Lamb waves are vertically polarized while shear horizontal waves are horizontally polarized.

Let us consider a plate with shear-free upper & lower surface as shown in the figure





fig 12 free body diagram of a small area, extracted from the plate

plate thickness: $2d$

Eqn. of motion for an isotropic elastic motion is given by:

$$\mu \nabla^2 u + (\lambda + \mu) \nabla \nabla \cdot u = f \frac{\partial^2 u}{\partial t^2} \quad (1)$$

where λ, μ - Lamé's constant

f - mass density

u - displacement vector

Assuming the displ. vector as below:

$$u = \nabla \Phi + \nabla \times H \quad (2)$$

where Φ & H are potential functions. and given by :

$$\Phi = f(y) e^{i(kx - \omega t)}$$

$$H = \left(h_x(y) i + h_y(y) j + h_z(y) k \right) e^{i(kx - \omega t)} \quad (3)$$

where ω : circular frequency
 k : wave number

$$\text{wave speed, } c = \omega/k$$

Assuming $(\omega, \mathbf{E}, \mathbf{C})$, governing Eqs are now written by:

$$\nabla^2 \Phi = \frac{1}{C_p^2} \frac{\partial^2 \Phi}{\partial t^2}$$

$$\nabla_H^2 = \frac{1}{C_s^2} \frac{\partial^2 H}{\partial t^2}$$

(4)

$$\nabla \cdot \mathbf{H} = 0$$

for the plane strain, (which is \mathbb{Z} invariant)


Eqs (A) now reduces to the following form:

$$f'' - \xi^2 f = -\frac{\omega^2 f}{C_p^2}$$

$$h_x'' - \xi^2 h_x = \frac{-\omega^2 h_x}{C_s^2}$$

$$h_y'' - \xi^2 h_y = \frac{-\omega^2 h_y}{C_s^2}$$

$$h_z'' - \xi^2 h_z = \frac{-\omega^2 h_z}{C_s^2}$$



where

C_p : Pressure wave speed
- longitudinal component

$$C_p^2 = \frac{\lambda + 2\mu}{\rho}$$

$$C_s^2 = \mu / \rho$$

C_s = Shear wave speed
= transverse component

Summary

- Non-destructive Evaluation methods
- Ultrasonic waves — monitoring purposes
- different form of waves
 - guided waves
-

