

## Module 4 : Sensors and Controllers in Robots

### Lecture 10 : Incremental encoders and position, velocity sensors, external state sensors

#### Objectives

In this course you will learn the following

- Internal State Sensing
- Position
- Incremental Encoders
- Position Decoding
- Velocity Measurements
- Velocity from encoder
- Acceleration Sensing
- External State Sensing


#### Internal State Sensing

##### Position

- Potentiometer
- Absolute encoders
  - Binary Vs. Gray Code
- Incremental Encoders

#### Incremental Encoders

- Initial Position Uncertain
- More Processing
- Less Expensive



- **Velocity from encoder**

Output pulse frequency  $\propto$  Speed. Use frequency to Voltage converter.

- AD451 FVC DC to 10 KHz
- Software estimate
  - Based on current & previous positions, higher order estimation of derivative.
  - Higher delay
  - Sampling time

### **Acceleration Sensing**


- Generally acceleration is not specified.
- Measured using 'accelerometers' – device having a known mass supported on springs. The deflection measured using arrangement similar to LVDT.
- Angular Acceleration not measured directly.
- Useful if play in transmission or flexible links.

### **External State Sensing**

- Vision, Touch
- Taste, smell, feel, slip, forces
- Advantages of Tactile sensing over Vision feedback

- More direct
- Fewer data
- Cleaner image
- Ruggedness
- Dynamic range
- Repeatability (Hysteresis)

### Proximity Rod Tactile Sensor



Low resolution Binary or Gray Image

Sense Part orientation

Figure 10.1.6

### Recap

In this course you have learnt about

- Internal State Sensing
- Position
- Incremental Encoders
- Position Decoding
- Velocity Measurements
- Velocity from encoder

- Acceleration Sensing
- External State Sensing

Congratulations, you have finished Lecture 10. To view the next lecture select it from the left hand side menu of the page

### Velocity Measurements

- Permanent Magnet DC Motor working as a generator.
- Each armature coil giving rectified DC
- Increase No. of coils (19-23) ripple < 1%
- Reduce Iron in armature => Inductance reduces, No. of coils increases





Figure 10.1.4



**Figure 10.1.5**