reviewer4@nptel.iitm.ac.in ▼ Courses » Manufacturing Strategy FAQ Announcements Course Ask a Question **Progress** Unit 7 - Week 6 Register for **Assignment 6 Certification exam** The due date for submitting this assignment has passed. Due on 2019-04-10, 23:59 IST. Course As per our records you have not submitted this outline assignment. 1) Deming's idea of improving competiveness through quality is based on ....... How to access 1 point the portal Eliminating waste Week 1 Reducing variation Week 2 Involvement of all All of the above Week 3 No, the answer is incorrect. Week 4 Score: 0 **Accepted Answers:** Week 5 Reducing variation Week 6 2) Which of the following is correct with reference to Deming's view of quality? 1 point Deming's Cease dependence on inspection to achieve quality Approach to Inspection is key to reduce variation Quality Variations can be reduced by precise machines. **Business** Excellence None of the above Awards **Process Choice** No, the answer is incorrect. Score: 0 **Process Choice Accepted Answers:** : 3 Dimensional View Cease dependence on inspection to achieve quality Product 3) What do you mean by PDCA? 1 point Profiling Plan Do Check Act Assignment 6 Prepare Do Control Act Solution of Prepare Do Check Act Assignment 6 Plan Do Control Act © 2014 NPTEL - Privacy & Terms - Honor Code - FAQs -A project of In association with

Funded by

Session	Japan	
	China	
	O U.K.	
	USA	
	No, the answer is incorrect.	
	Score: 0	
	Accepted Answers:	<b>A</b>
	USA	 1 point
	5) Which of the following was not originally included sector under Malcolm Baldrige National Quality Award?	
		<b>R</b>
	Education	<u> </u>
	Manufacturing	
	Service company	显
	Small business	
	No, the answer is incorrect.  Score: 0	
	Accepted Answers:	
	Education	
	6) Which of the following is correct for low standardized products?	1 point
	These products are generally produced in large volumes.	
	These products are generally produced in small volumes.	
	These products are generally produced on special purpose machines.	
	None of the above	
	No, the answer is incorrect. Score: 0	
	Accepted Answers:	
	These products are generally produced in small volumes.	
	7) Which type of manufacturing process is suitable for low standardized products?	1 point
	Batch process	
	Assembly line	
	Job shop	
	Continuous flow	
	No, the answer is incorrect. Score: 0	
	Accepted Answers: Job shop	
	8) Which of the following is not a dimension of three dimensional generic manufacturing strategy framework?	1 point
	Process structure complexity	
	Product line complexity	
	Marketing complexity	
	Organizational Scope	
	No, the answer is incorrect.	

