NPTEL -	Mecha	nical	Engine	ering	- For	ming
INFILL -	IVICUITO	IIIICai	LIIGIIIC	cillig.	- 1 01	IIIIIII

Stress transformation and Mohr's circle for stresses

R. Chandramouli Associate Dean-Research SASTRA University, Thanjavur-613 401

Table of Contents

1.Quiz:	3
1.\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	J

Strain Transformation equations:

1.Quiz:

- 1. What is meant by deviatoric stress?
- 2. Hydrostatic stress is known not to cause yielding. Then why hydrostatic extrusion is used?
- 3. When a steel ball of 2.5 cm diameter is subjected to a hydrostatic pressure of 12 GPa, what will be its final diameter?
- 4. Name some forming processes which use plane strain deformation.