Sheet metal operations - Cutting and related processes

R. Chandramouli Associate Dean-Research SASTRA University, Thanjavur-613 401

Table of Contents

1.Quiz-Key

- 1. Name three important sheet metal operations. Bending, cutting, drawing.
 - 2. For obtaining straight, vertical edge during blanking, what clearance is preferred? High or low?

Low clearance.

- 3. Why are the edges of shearing punches provided an angle? To reduce the punch force by reducing the area of contact between punch and sheet at a given time.
- 4. What is fine blanking? Blanking with very less clearance and holding the sheet for achieving high accuracy and good edge quality is called fine blanking.